


*File - Streets Mke - 1958*

# BROUGHTON PRINTING COMPANY



1016 SOUTH 6th STREET • MINNEAPOLIS 4, MINNESOTA • FEDERAL 2-8381 • ESTABLISHED 1883

April 25, 1958

Mr. Warren C. Hyde,  
Village Manager  
Village of Edina  
4801 West 50th Street  
Edina 24, Minnesota

Dear Mr. Hyde:


After writing you on April 14, I certainly hate to tell you that the blacktop which was installed on Windsor and Code Avenues is still unsatisfactory. The enclosed picture shows the water standing on Olof Andersons side of the street, corner of Windsor and Code. This picture was taken on Saturday, April 19. Should you recall, we had a slight shower the preceding day. I would guess the water will stand in the street, as shown in the picture, for a period of three or four days. It looks like it will be necessary to rebuild this entire piece of road, as stated in ~~my~~ letter of April 3rd. In your letter of April 8, you mentioned doing some work in June. Perhaps it is your intention of putting the road in first class condition at that time. If this is not your plan, please advise.

Yours sincerely,

Herb Broughton

HOB:ct

# BROUGHTON PRINTING COMPANY



1016 SOUTH 6th STREET • MINNEAPOLIS 4, MINNESOTA • FEDERAL 2-8381 • ESTABLISHED 1883

April 14, 1958

Mr. Warren C. Hyde,  
Village Manager  
Village of Edina  
4801 West 50th Street  
Edina 24, Minnesota

Dear Mr. Hyde:

Thank you very much for your letter of April 8. The blacktopping work was done the middle of last week. I was very much pleased to have you give this matter your prompt attention. You can be assured that it is much more pleasant to drive in the garage without tracking in water and mud.

Thank you very much for your consideration.

Yours sincerely,

A handwritten signature in dark ink, appearing to read "Herb Broughton", with a stylized, flowing script. The signature is written over the printed name "Herb Broughton".

Herb Broughton

HOB:ct