



BUILDING-STRUCTURE INVENTORY FORM
NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
DIVISION FOR HISTORIC PRESERVATION
(518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. _____
QUAD _____
SERIES _____
NEG. NO. _____

Photos
White

YOUR NAME: STEPHANIE W. MAURCI DATE: AUGUST 1987

YOUR ADDRESS: _____
P.O. Box 88
ORGANIZATION (if any): Poughkeepsie, NY 12602
914-471-1630
***** Dutchess County Historical Society

IDENTIFICATION


- 1. BUILDING NAME(S): _____
- 2. COUNTY: DUTCHESS TOWN/CITY: CLINTON VILLAGE: NA
- 3. STREET LOCATION: WALNUT DRIVE (EAST & WEST SIDES) @ 1/2 M. SOUTH OF
- 4. OWNERSHIP: a. public b. private (NYC) MEADOWBROOK LANE.
- 5. PRESENT OWNER: GEORGE BEAN ADDRESS: 1009 14th 206. #3280 (W & H)
- 6. USE: Original: FARM / RESIDENCE Present: SAME
- 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No
Interior accessible: Explain _____

DESCRIPTION

- 8. BUILDING MATERIAL: a. clapboard b. stone c. brick d. board and batten
e. cobblestone f. shingles g. stucco other: _____
- 9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints
b. wood frame with light members ADDIT. NYC: 212-724-5803 (W)
c. masonry load bearing walls
d. metal (explain) _____
e. other _____
- 10. CONDITION: a. excellent b. good c. fair d. deteriorated
- 11. INTEGRITY: a. original site b. moved if so, when? _____
c. list major alterations and dates (if known):
E 1800 + M 1800 + E 1900

12. PHOTO:

13. MAP:



14. THREATS TO BUILDING: a. none known b. zoning c. roads
 d. developers e. deterioration
 f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:
 a. barn b. carriage house c. garage
 d. privy e. shed f. greenhouse
 g. shop h. gardens
 i. landscape features: OLD TREES & SHRUBS
 j. other: STONE WALLS, WOOD FENCE

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
 a. open land b. woodland
 c. scattered buildings
 d. densely built-up e. commercial
 f. industrial g. residential
 h. other: AGRICULTURE

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
 (Indicate if building or structure is in an historic district)
STONE CISTERN UNDER LOWER PART OF SMALL NORTH WING;
CENTRAL HALL BEING RESTORED; ? APPEARS NOT TO HAVE BEEN A DOOR SINCE
CELLAR ENTRY IS DIRECTLY UNDER IT; (AT OPP. END OF HALL IN WEST SIDE)
ON DECK; DINING ROOM (NORTH SIDE) HAS STAIR TO 2ND FLOOR;

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
RESIDED @ 1960 & CENTER HALL WALL TAKEN OUT;
WIDE BOARD FLOORS; WINDOWS 6/6 W/ MUCH OLD GLASS; M/L 1800
FRONT DOOR W/ LG. SIDELITES;


SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1800
 ARCHITECT: UNK.
 BUILDER: UNK.

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

PREV. OWNERS:

1867 map -> S. & A. HADDON
1876 map -> "ELM GROVE"



ASH LOSSER HAS M/L 1800 PHOTO; OWNER HAS COPY ...
ZHOYT

21. SOURCES: SEND LANDSCAPE INFO ...
* REFER TO NETL @ SHPO FOR MORE INFO -

FINE VIEW W/ OUTBLDG'S & LANDSCAPE

22. THEME:

